




# Lenovo IdeaPad G50-45 Screen Replacement

Once you're done with this guide you should be able to efficiently replace your screen.

Written By: Jessy McDermott





## TOOLS:


- [iFixit Opening Tools](#) (1)
- [Phillips #2 Screwdriver](#) (1)



## PARTS:


- [Screen Replacement](#) (1)

## Step 1 — Screen



- Remove the plastic lining around the screen (bezel) by using a small wedge under it and lifting up.

## Step 2






- Finish removing it by using your hand on the inside of the screen and popping off the bezel.
- If one part won't pop off start on the opposite side and work your way back to the area that is stuck.
- The plastic on the hinges will pop off with the rest of the bezel.

## Step 3



- It'll look like this

## Step 4



- Unscrew the 4 screws in each corner of the screen



## Step 5



- Peel sticker attaching the connector to the back of the screen.
- Disconnect the cable connecting the screen to the computer, there might be two.

## Step 6



- Test the new screen by turning it on before putting on the bezel!

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-17 05:06:38 AM.